

Questions & Answers
SITE NAME – Bentz Motors
COMM #54826-9999-28
BRRTS # 03-03-000395

Question: The Minimum Remedial Requirement included providing a cost for the replacement and development of monitoring wells MW-1 and MW-2 if the wells are removed because of the excavation. Both well are flush mounted and installed to a depth of 18 feet, but no line item was provided on the 2nd page in case it is decided not to replace the wells.

Answer: A separate line item cost should be added to the 2nd page of the bid proposal for the replacement and development of MW-1 and MW-2. The replacement costs would be included in the bid cap only if the monitoring wells need to be replaced because of the excavation in the area.