

Questions & Answers
Broadbent Oil
COMM # 53581-0674-77
BRRTS # 03-53-000536

Question: The bid specifies, "Please install one groundwater table monitoring well in the approximate area of excavation sample #6 and one soil boring approximately 10 feet west of excavation soil sample #102." The location of the soil boring requested will be less than 5 feet from the requested groundwater table monitoring well. Is this correct? Please clarify if you are requiring 2 soil borings with each of them being sampled at 4 feet below grade with samples collected every 2-4 feet thereafter, then converting one boring to a groundwater monitoring well or if you are only requiring 1 soil boring converted to a groundwater monitoring well with appropriate sampling. Please verify the location of the well and soil boring.

Answer: This is a typo in the minimum remedial requirement section. The relationship of the soil boring location is incorrectly stated, the soil boring location is to be to the **east** of excavation sample #102. The second sentence of the second paragraph should read, "Please install one groundwater table monitoring well in the approximate area of excavation soil sample #6 and one soil boring approximately 10 feet east of excavation soil sample #102." The department is requiring a total of 2 soil borings. The monitoring well boring can be blind drilled to 4 feet below grade with headspace soil samples collected every 2-4 feet until the groundwater table is reached. The second soil boring shall begin sample collection at ground surface with headspace samples collected every 2-4 feet until the groundwater table is reached.

Question: If NETI-16 cannot be found or is damaged beyond repair does it need to be replaced?

Answer: The installation of a replacement monitoring well is not required in this scope of work.