

Questions & Answers
Friday Canning Co. Site #2
Comm Number: **54112-9517-31**
BRRTS Number: **03-38-001701**

LIST THE QUESTION FOLLOWED BY THE ANSWER. INDENT THE ANSWER. USE ARIAL 12 PT FONT.

- 1) Who is the lender?

Unknown as there is no lender listed in DCOM's records.

- 2) Has any claim been filed?

Two claims have been filed, and one claim is on appeal.

- 3) If claim(s) is/are filed, is it possible to divide the site investigation and remedial costs?

N/A

- 4) Will the Department provide the previous maps and tables on a disc to the hired successful bidder?

No, but the case file can be reviewed at the Peshtigo Service Center Monday through Friday, 7:45 am – 4:30 pm, by appointment.

- 5) Where are two active tanks, piping, and pump island located?

As indicated in the site investigation information available for copying, there is an active AST system located northeast of Site #2. The Department has not been provided any information on another active tank system at the property.

- 6) Where are Site #1 and Site #2 located?

As indicated in the site investigation information available for copying, both sites exist at the Friday Canning Corporation property in Coleman. Site #1 is located northwest of Site #2.

- 7) Is contamination at Site #2 due to the existing tanks?

The information provided to the Department indicates a release from the former tank at Site #2 has occurred. Only the release from Site #2 is being addressed in this bid.

8) Are any ASTs existing at the site?

As indicated in the site investigation information available for copying, there is an existing AST system located northeast of the source area for Site #2.

9) Are the three tank locations (tank #1 through #3) denoted the three tanks removed in 1991-1992?

As indicated in the site investigation information available for copying, there were three tank systems removed in the early 1990's, Tanks #1, 2, and 3.

10) Where were the old piping and pump islands?

As indicated in the site investigation information available for copying, Site #2 had a pump at the southeast corner of the UST bed.