



Inspection & Testing

34. **SPS 382.20(1) - 5/20/99**

Plan submittal/inspection of Native American land? See PDF file.

40. **SPS 382.21(2)(a) - 5/10/07**

May a cross connection control assembly remain in service if it is not code compliant now, but was code compliant when it was installed? A cross connection control device may remain if it was code compliant at the time of installation unless the cross connection device is failing or is being replaced. See [PDF file](#) about dates of when cross connection control devices of various types were code compliant.

41. **SPS 382.21(3) - 6/6/00**

What needs replacement in existing installations? [PDF file](#) to help an inspector know what needs to be replaced if found during inspection of an existing installation.

128. **SPS 382.41(3) - 11/24/04**

When does cross connection control need to be modified to be code compliant when remodeling or repairing a plumbing system? If the piping system is being cut to remove or repair the backflow prevention device or assembly, the cross connection control must be made code compliant to the code in effect at the time of the repair. If a union is installed that would allow removal of the device or assembly without cutting the piping system, the existing device or assembly may be returned to service.