

Questions & Answers
Von Holzen Dairy
54986-9768-58-A
03-71-108381

- Q. Under 3) Minimum Remedial Requirements, you seem to be suggesting that a consultant could get the site closed by sampling MW-4R for four quarterly rounds, and MW-5 for to semi-annual rounds (assuming correct data trends), only, and that no other wells need to be sampled during this time? If this is an incorrect interpretation, please clarify.
- A. This interpretation is correct provided depth to groundwater data obtained from MW-4R and MW-5 does not suggest a shift in groundwater flow direction. With the exception of one anomalous sampling event, groundwater contamination has not been observed in other monitoring wells above the PAL over the course of 12 sampling events.