

Questions & Answers
SITE NAME Arpin Dairy Inc
COMM # 54410-9665-13
BRRTS #03-72-000732

Question: The bid table in the Round 43 bid specs does not include a line item for mw installation

Answer: **INSERT THE COST OF THE MONITORING WELL INSTALLATION AS ITEM #11 AND THEN THE TOTAL COST AS #12.**