

Questions & Answers
ForeWay Express Inc
COMM # 53714-3125-02
BRRTS # 03-13-282707

Question: At a minimum, what parameters do you want measured to document natural attenuation?

Answer: The minimum parameters expected for this scope of work include dissolved oxygen, nitrate, nitrite, ferrous iron, sulfate, pH, temperature and conductivity.