

Goffin Oil, 54848-1328-07

1. Who is the lender?

State Bank of Chilton (Last known)

2. Has any claim been filed?

Yes

3. If claim (s) is/are filed, is it possible to divide the site investigation and remedial costs?

Yes, this can usually be done.

4. Will the Department provide the previous maps and tables on a disc to the hired successful bidder?

The Department does not have the maps or tables in electronic format. Only what is available in the case files at 107 Sutliff Ave., Rhinelander, WI, will be made available to the consultant for their review and copying at that location.

5. Who is the consultant?

Envirogen

6. Is there any methodology developed to segregate TCE cost?

No.

7. Do you want soil samples collected for field screening and/or for quantitative analysis when the replacement well for MW-6 is installed? If so, what lab tests would you like to see conducted?

Field screening should include PID (or similar) analysis using a splitspoon every two feet. Two samples should be collected, one at the water table and one where PID readings are highest, for VOCs, PAHs and lead.

8. Should ground water samples be analyzed for TCE? If not, will the closure committee question why no further TCE sampling was conducted?

From the information collected during the SI it appears that the TCE contamination is coming from off-site up-gradient (south). Unless soil sampling at replacement well MW-6 or some other information is revealed during the remedial action, showing a source area of TCE on site, additional TCE analysis will not be required for closure of this site.