

Questions & Answers  
UC Bulk Facility  
53536-1163-65  
02-54-150621

Question: Do you have any additional information about the hand pump well? What is its depth, diameter, and construction?

Answer: The entire hand pump apparatus is still in place, although it is not in working order. The casing is steel and approximately 6 inches in diameter. The steel casing is set into an approximately 3-foot by 3-foot concrete pad, on which the hand pump stand is still mounted. The depth of the casing is unknown. The depth to groundwater beneath the site is reported as approximately 6 feet below grade and the depth to bedrock is reported as approximately 12 feet below grade. It is assumed that the wells drop pipe is still in place. Other than that, no additional construction details are available.

Question: Do any barrels of investigative waste remain on-site from previous consulting activities?

Answer: No.