
Updated Warning to All Customers

Dear valued customer:

Recently, Cover-All Building Systems Inc. began a review of designs utilized in some of its building lines. We are no longer able to fund the completion of this review. Although a review is not complete, there has been an initial determination that some of the structural members and connections for some of the spans of certain buildings manufactured by Cover-All Building Systems Inc. may not meet the present combined wind and snow load capacity requirements of applicable building codes.

In light of this initial determination, Cover-All Building Systems Inc. recommends that you engage a structural engineer to perform an analysis of your building to determine whether it meets all applicable building code requirements.

Because we have not reviewed all of our building lines, we are not in a position to make specific safety recommendations for all building lines. However, we encourage you to take precautions when using your building during any severe weather, including snow, sleet, freezing rain and high wind conditions. The best precaution to take is to avoid using your building during severe weather as well as when there is any build up of snow or ice on the roof or sides of your building.

For more information please visit www.coverallfacts.net where a copy of a customer safety warning that relates to other Cover-All buildings is posted for review, or call 877-551-5856. If specific safety recommendations for our different building lines become available in the future, we intend to post them on www.coverallfacts.net, as well.

Sincerely,
Nathan Stobbe
President and Chief Executive Officer